

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burlleson, TX 76028
1.	Basin, Ground, 5.0 Vol MG, 165' Tank Dia., 38.3' Tank Height, Column Height N/A, 38.3' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) See Note 1 below - applies to all tanks Cleaning Cost In-service (not drained) See Note 1 below - applies to all tanks Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 12,000.00 100.00 300.00 4,400.00 100.00 17,100.00	892.00 25,246.00 2,571.00 1,251.00 12,119.00 4,197.00 46,276.00	BID NOT TABULATED- DOES NOT MEET SPECIFICATIONS	BID WITHDRAWN
2.	Culebra, Ground, 0.05 Vol MG, 17" Tank Dia, 32.5 Tank Height, Column Height N/A, 32.5 Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 2,400.00 100.00 300.00 600.00 100.00 3,700.00	892.00 3,474.00 274.00 1,251.00 2,483.00 98.00 8,472.00		
3.	Culebra 1, Ground, 0.05 Vol MG, 17' Tank Dia, 32.5 Tank Height, Column Height N/A, 32.5 Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 2,400.00 100.00 300.00 600.00 100.00 3,700.00	892.00 3,474.00 274.00 1,251.00 2,483.00 98.00 8,472.00		
4.	Culebra HPT, Hydropneum, 0.01 Vol MG, 10' Tank Dia, 17'L Tank Height, Column Height N/A, 17L Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation TOTAL	200.00 1,200.00 100.00 1,500.00	892.00 3,200.00 274.00 4,366.00		
5.	Fredericksburg, Elevated RW, 1.0 Vol MG, 74' Tank Dia., 35' Tank Height, 59' Column Height, 97' Overall Height Inspection Cost Drained Drained Cleaning cost w/Water Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation TOTAL	200.00 5,700.00 100.00 6,000.00	892.00 13,873.00 721.00 15,486.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burlleson, TX 76028
6.	IH-10, Ground, 3.0 Vol MG, 91' Tank Dia, 72.4' Tank Height, Column Height N/A, 72.4' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (no drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 9,242.00 100.00 300.00 2,500.00 100.00 12,442.00	892.00 22,826.00 1,803.00 1,251.00 5,485.00 1,276.00 33,533.00	BID NOT TABULATED - DOES NOT MEET SPECIFICATIONS	BID WITHDRAWN
7.	Indian Springs, Standpipe, 3.0 Vol MG, 64' Tank Dia, 131.5' Tank Height, Column Height N/A, 131.5' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 11,248.00 100.00 300.00 3,000.00 100.00 14,948.00	892.00 16,061.00 1,803.00 1,251.00 4,096.00 631.00 24,734.00		
8.	Marshall Tank, Ground, 0.55 Vol MG, 55' Tank Dia, 32' Tank Height, Column Height N/A, 32' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 7,131.00 100.00 300.00 1,200.00 100.00 9,031.00	892.00 17,460.00 721.00 1,251.00 3,741.00 466.00 24,531.00		
9.	Naco, Ground, 7.5 Vol MG, 165' Tank Dia, 52.2' Tank Height, Column Height N/A, 52.2' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 11,472.00 100.00 300.00 5,000.00 100.00 17,172.00	892.00 28,429.00 3,383.00 1,251.00 12,119.00 4,197.00 50,271.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burlleson, TX 76028
10.	Sasse, Ground, 2.0 Vol MG, 92.3' Tank Dia, 43.8' Tank Height, Column Height N/A, 43.8' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 7,192.00 100.00 300.00 2,400.00 100.00 10,292.00	892.00 11,643.00 1,443.00 1,251.00 5,546.00 1,305.00 22,080.00	BID NOT TABULATED- DOES NOT MEET SPECIFICATIONS	BID WITHDRAWN
11.	Avenue B, Ground RW, 0.4 Vol MG, 54' Tank Dia, 28.5' Tank Height, Column Height N/A, 28.5' Overall Height Inspection Cost Drained Drained Cleaning cost w/Water Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation TOTAL	200.00 6,500.00 100.00 6,800.00	892.00 10,639.00 721.00 12,252.00		
12.	Helotes Park II, Elevated, 0.1 Vol MG, 20' Tank Dia, 32' Tank Height, 76 Column Height, 108' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 3,719.00 100.00 300.00 1,300.00 100.00 5,719.00	892.00 17,694.00 721.00 1,251.00 2,564.00 244.00 23,366.00		
13.	Lockhill Tank, Elevated, 1.5 Vol MG, 91.3' Tank Dia, 46' Tank Height, 149' Column Height, 195' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 10,630.00 100.00 300.00 2,500.00 100.00 13,830.00	892.00 13,006.00 1,082.00 1,251.00 8,782.00 2,808.00 27,821.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burleson, TX 76028
14.	Maltsberger, Ground, 7.5 Vol MG, 165' Tank Dia, 48' Tank Height, Column Height N/A, 48' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 15,972.00 100.00 300.00 4,900.00 100.00 21,572.00	892.00 26,935.00 3,382.00 1,251.00 12,119.00 4,197.00 48,776.00	BID NOT TABULATED- DOES NOT MEET SPECIFICATIONS	BID WITHDRAWN
15.	Menger Tank, Elevated, 1.5 Vol MG, 88' Tank Dia, 70 Column Height, 116.5' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 8,630.00 100.00 300.00 2,400.00 100.00 11,730.00	892.00 17,513.00 1,082.00 1,251.00 8,390.00 2,626.00 31,754.00		
16.	Persall, Ground RW, 2.5 Vol MG, 120' Tank Dia, 33' Tank Height, Column Height N/A, 33' Overall Height Inspection Cost Drained Drained Cleaning cost w/Water Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation TOTAL	200.00 8,500.00 100.00 8,800.00	892.00 16,152.00 1,083.00 18,127.00		
17.	Ranch Town II, Ground, 1.0 Vol MG, 75' Tank Dia, 30' Tank Height, Column Height N/A, 30' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 5,787.00 100.00 300.00 1,300.00 100.00 7,787.00	892.00 11,337.00 1,082.00 1,251.00 4,604.00 903.00 20,069.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burlleson, TX 76028
18.	Redland, Elevated, 2.5 Vol MG, 105' Tank Dia, 50' Tank Height, 46' Column Height, 96' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 7,000.00 100.00 300.00 3,900.00 100.00 11,600.00	892.00 19,838.00 2,114.00 1,251.00 11,134.00 3,739.00 38,968.00	BID NOT TABULATED- DOES NOT MEET SPECIFICATIONS	BID WITHDRAWN
19.	Seale, Ground, 3.0 Vol MG, 90' Tank Dia, 64.5' Tank Height Column Height N/A, 64.5' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 10,242.00 100.00 300.00 2,200.00 100.00 13,142.00	892.00 20,564.00 2,114.00 1,251.00 5,425.00 1,249.00 31,495.00		
20.	Cedar Creek, Ground, 0.33 Vol MG, 19' Tank Dia, 17.7' Tank Height, Column Height N/A, 17.7' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 4,181.00 100.00 300.00 900.00 100.00 5,781.00	892.00 7,036.00 549.00 1,251.00 2,536.00 122.00 12,386.00		
21.	Coliseum, Elevated RW, 0.5 Vol MG, 75' Tank Dia, 43' Tank Height, 97' Column Height, 140' Overall Height Inspection Cost Drained Drained Cleaning cost w/Water Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation TOTAL	200.00 9,000.00 100.00 9,300.00	892.00 16,653.00 721.00 18,266.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burlleson, TX 76028
22.	Encino Park Old, Standpipe, 0.5 Vol MG, 38' Tank Dia, 64' Tank Height, Column Height N/A, 64' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 5,524.00 100.00 300.00 1,300.00 100.00 7,524.00	892.00 8,948.00 721.00 1,251.00 3,216.00 223.00 15,251.00	BID NOT TABULATED - DOES NOT MEET SPECIFICATIONS	BID WITHDRAWN
23.	Inspiration Tank, Ground, 2.2 Vol MG, 83' x 143' Tank Dia, 31.2' Tank Height, Column Height N/A, 31.2' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 11,254.00 100.00 300.00 3,000.00 100.00 14,954.00	892.00 16,984.00 1,691.00 1,251.00 5,023.00 1,062.00 26,903.00		
24.	Lions Field Tank, Elevated, 1.5 Vol MG, 88' Tank Dia, 46.5' Tank Height, 88' Column Height, 134.5' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 10,630.00 100.00 300.00 2,400.00 100.00 13,730.00	892.00 19,816.00 1,268.00 1,251.00 8,390.00 2,626.00 34,243.00		
25.	Marbach, Ground, 5.0 Vol MG, 165' Tank Dia, 31.2' Tank Height, Column Height N/A, 31.2' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 12,910.00 100.00 300.00 4,600.00 100.00 18,210.00	892.00 25,718.00 2,537.00 1,251.00 12,119.00 4,197.00 46,714.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burleson, TX 76028
26.	Market Street, Ground, 0.88 Vol MG, 61.2' Tank Height, Column N/A, 61.2' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 5,062.00 100.00 300.00 1,000.00 100.00 6,762.00	892.00 7,703.00 721.00 1,251.00 3,972.00 574.00 15,113.00	BID NOT TABULATED- DOES NOT MEET SPECIFICATIONS	BID WITHDRAWN
27.	Medical, Elevated, 1.0 Vol MG, 75.5 Tank Dia, 42' Tank Height, 110' Column Height, 152' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 9,787.00 100.00 300.00 1,300.00 100.00 11,787.00	892.00 9,630.00 721.00 1,251.00 6,735.00 1,857.00 21,086.00		
28.	Micron, Ground, 5.00 Vol MG, 165' Tank Dia, 32' Tank Height, Column Height, 32' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 12,910.00 100.00 300.00 4,800.00 100.00 18,410.00	892.00 33,982.00 2,537.00 1,251.00 12,119.00 4,197.00 54,978.00		
29.	Pinn Road, Ground RW, 2.8 Vol MG, 84' Tank Dia, 80' Tank Height, Column Height N/A, 80' Overall Height Inspection Cost Drained Drained Cleaning cost w/Water Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation TOTAL	200.00 10,000.00 100.00 10,300.00	892.00 26,818.00 2,537.00 30,247.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006
 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burleson, TX 76028	
30. Mission, Ground, 5.00 Vol MG, 147' Tank Dia. 48' Tank Height, Column Height N/A, 48' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 12,910.00 100.00 300.00 4,800.00 100.00 18,410.00	892.00 24,711.00 2,114.00 1,251.00 10,256.00 3,331.00 42,555.00	BID NOT TABULATED- DOES NOT MEET SPECIFICATIONS	
31. Piper Meadow, Ground, 0.05 Vol MG, 19' Tank Dia, 24.3' Tank Height, Column Height N/A, 24.3' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 3,050.00 100.00 300.00 1,100.00 100.00 4,850.00	892.00 3,554.00 274.00 1,251.00 2,483.00 98.00 8,552.00		BID WITHDRAWN
32. Pipestone, Standpipe, 3.00 Vol MG, 84' Tank Dia, 75.9' Tank Height, Column Height N/A, 75.9' Overall Height Inspection Cost Drained Drained Cleaning cost w/Floran or equal* Interior/Exterior Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	200.00 11,648.00 100.00 300.00 3,500.00 100.00 15,848.00	892.00 25,268.00 2,325.00 1,251.00 5,311.00 1,088.00 36,135.00		
TOTAL FOR ITEMS 1 - 32	352,731.00	853,278.00	0.00	

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Triennial Contract for
 FOR: Water Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2008)
 DATE: 3:00 p.m., March 7, 2006
 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Extech, LLC 490 Industrial Park Rd. Deep River, CT 06417	KLM Engineering, Inc. P.O. Box 897 Lake Elmo, MN 55042	US Underwater Services, Inc. 101 NE Haskew Burleson, TX 76028
--	--	--	---

	EMERGENCY UNDERWATER INSPECTION SERVICES		
33.	Mobilization for emergency underwater inspection services (on site within 48 hours of notification) Elevated Tank Per Trip X(2) trips	500.00 1,000.00	5,300.00 10,600.00
34.	Hourly rate for emergency underwater inspection services (Elevated tank) Potable water Per Hour X(24) hrs.	190.00 4,560.00	275.00 6,600.00
35.	Mobilization for emergency underwater inspection services (on site within 48 hours of notification) Ground storage tank Per Trip X(2) trips	500.00 1,000.00	5,300.00 10,600.00
36.	Hourly rate for emergency underwater inspection services (Ground storage tank) Potable water Per Hour X(24) hrs.	190.00 4,560.00	275.00 6,600.00
	TOTALS (FOR EMERGENCY SERVICES)	11,120.00	34,400.00
	PROPOSED CLEANING AGENT	Floran	Floran
	Terms	1% 20 days	Net 30 days
	Delivery Days	30 days	

BID NOT TABULATED-
 DOES NOT MEET SPECIFICATIONS

BID WITHDRAWN

BID INVITATIONS MAILED TO AND/OR PICKED UP BY:

Chris Harlen
 Extech, LLC
 International Diving Services
 KLM Engineering Inc.
 US Underwater Services, Inc.

Demandstar
 SAWS Website