

about what is in your drinking water. yelps you become knowledgedble this report. We hope this information (FPA) required tests and is presented in Environmental Protection Agency the data from the most recent U.S. The analysis was made by using (SWAS) provides its customers. of water San Antonio Water System This report is a summary of the quality



P.O. Box 2449 San Antonio, TX 78298-2449

# **NORTH SAN ANTONIO HILLS**



NORTH



A REFRESHING TOMORROW





SAN ANTONIO WATER SYSTEM | NORTH SAN ANTONIO HILLS

# SOURCE OF DRINKING WATER

The sources of drinking water (both tap water and bottled water) include rivers, lakes, streams, ponds, reservoirs, springs, and wells. As water travels over the surface of the land or through the ground, it dissolves naturally-occurring minerals and, in some cases, radioactive material, and can pickup substances resulting from the presence of animals or from human activity.

**2012 WATER QUALITY REPORT** 

Contaminants that may be present in source water include:

- Microbial contaminants, such as viruses and bacteria, which may come from sewage treatment plants, septic systems, agricultural livestock operations, and wildlife
- Inorganic contaminants, such as salts and metals, which can be naturally-occurring or result from urban storm water runoff, industrial or domestic wastewater discharges, oil and gas production, mining, or farming
- Pesticides and herbicides, which may come from a variety of sources such as agriculture, urban storm water runoff,

#### **ALL DRINKING WATER MAY CONTAIN CONTAMINANTS**

When drinking water meets federal standards, there may not be any health benefits to purchasing bottled water or point of use devices. Drinking water, including bottled water, may reasonably be expected to contain at least small amounts of some contaminants. The presence of contaminants does not necessarily indicate that water poses a health risk. More information about contaminants and potential health effects can be obtained by calling the EPA's Safe Drinking Water Hotline (800-426-4791).

# SECONDARY CONSTITUENTS

Many constituents (such as calcium, sodium, or iron), which are found in drinking water, can cause taste, color, and odor problems. The taste and odor constituents are called secondary constituents and are regulated by the State of Texas, not the EPA. These constituents are not causes for health concern. Therefore, secondaries are not required to be reported in this



and residential uses

- Organic chemical contaminants, including synthetic and volatile organic chemicals, which are by-products of industrial processes and petroleum production, and can also come from gas stations, urban storm water runoff, and septic systems.
- Radioactive contaminants, which can be naturallyoccurring or be the result of oil and gas production and mining activities

#### WHERE DO WE GET OUR DRINKING WATER?

The source of drinking water used by SAWS North San Antonio Hills is ground water from the Edwards Aguifer. A Source Water Susceptibility Assessment for your drinking water source(s) is currently being updated by the Texas Commission on Environmental Quality. This information describes the susceptibility and types of constituents that may come into contact with your drinking water source based on human activities and natural conditions.

The information contained in the assessment allows us to focus source water protection strategies. Some of this source water assessment information is available on Texas Drinking Water Watch at http://dww.tceq.state.tx.us/DWW/.

For more information on source water assessments and protection efforts at our systems, please contact us.

document, but they may affect the appearance and taste of vour water.

# **HEALTH INFORMATION ABOUT LEAD**

If present, elevated levels of lead can cause serious health problems, especially for pregnant women and young children. Lead in drinking water is primarily from materials and components associated with service lines and home plumbing. This water supply is responsible for providing high quality drinking water but cannot control the variety of materials used in plumbing components. When your water has been sitting for several hours, you can minimize the potential for lead exposure by flushing your tap for 30 seconds to two minutes before using water for drinking or cooking. If you are concerned about lead in your water, you may wish to have your water tested. Information on lead in drinking water, testing methods, and steps you can take to minimize exposure is available from the Safe Drinking Water Hotline or at http://www.epa.gov/safewater/lead.

# **SPECIAL NOTICE**

You may be more vulnerable than the general population to certain microbial contaminants, such as Cryptosporidium, in drinking water. Infants, some elderly or immuno-compromised such as those undergoing chemotherapy for cancer; those who have undergone organ transplants; those who are undergoing treatment with steroids; and people with HIV/AIDS or other immune system disorders can be particularly at risk from infections. You should seek advice about drinking water from your physician or health care provider. Additional guidelines appropriate means to lessen the risk of infection by Cryptosporidium are available from the Safe Drinking Water Hotline at 800-426-4791.

# DEFINITIONS

The following tables contain scientific terms and measures, some of which may require explanation.

ALG (Action Level Goal) - The level of a contaminant in drinking water below which there is no known or expected risk to health. ALGs allow for a margin os safety.

AL (Action Level) – The concentration of a contaminant which, if exceeded, triggers treatment or other requirements which a water system must follow.

MCLG (Maximum Contaminant Level **Goal)** – The level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

MCL (Maximum Contaminant Level)

- The highest level of a contaminant that is allowed in drinking water. MCLs are set as close to the MCLGs as feasible using the best available treatment technology.

**MRDLG (Maximum Residual** 

Disinfectant Level Goal) - The level of a drinking water disinfectant below which there is no known or expected risk to health. MRDLGs do not reflect the benefits of the use of disinfectants to control microbial contaminants.

MRDL (Maximum Residual

**Disinfectant Level)** – The highest level of a disinfectant allowed in drinking water. There is convincing evidence that addition of a disinfectant is necessary for control of microbial contaminants.

MFL – Million fibers per liter (a measure of asbestos)

**NA** – Not applicable

NTU – Nephelometric Turbidity Units **pCi/L** – Picocuries per liter (a measure of radioactivity)

**ppm** – Parts per million or milligrams per liter (mq/L)

**ppb** – Parts per billion or micograms per liter ( $\mu$ g/L)

**ppt** – Parts per trillion or nanograms per liter (ng/L)

**ppq** – Parts per quadrillion or picograms per liter (pg/L)

**II** – Treatment technique

# MAXIMUM RESIDUAL DISINFECTANT LEVEL

	Disinfectant	Year	Average Level	Minimum Level	Maximum Level	MRDL	MRDLG	Units	Source of Chemical	
	Chlorine residual, free	2011	1.2	0.7	1.8	4.0	<4.0	ppm	Disinfectant used to control microbes	

#### **COLIFORM BACTERIA**

Total Coliform: Total coliform bacteria are used as indicators of microbial contamination of drinking water because testing for them is easy. While not disease-causing organisms themselves, they are often found in association with other microbes that are capable of causing disease. Coliform bacteria are more hardy than many disease-causing organisms; therefore, their absence from water is a good indication that the water is microbiologically safe for human consumption.

Total Coliform: REPORTED MONTHLY TESTS FOUND NO TOTAL COLIFORM BACTERIA. Fecal Coliform: REPORTED MONTHLY TESTS FOUND NO TOTAL COLIFORM BACTERIA.

#### LEAD AND COPPER

Constituent	Date Sampled	MCLG	AL	90th Percentile	Number of Sites Over AL	Units	Violation	Likely Source of Contamination
Copper	2009	1.3	1.3	0.25	0	ppm	No	Erosion of natural deposits; leaching from wood p household plumbing systems
Lead	2009	0	15	3.7	0	ppb	No	Corrosion of household plumbing systems; erosion

#### SECONDARY AND OTHER CONSTITUENTS NOT REGULATED (Not associated with adverse health effects)

Constituent	Collection Date	Highest Level Detected	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination			
Aluminum	2010	<0.0013	<0.0013	0	0.05	ppm	No	Abundant naturally occurring element			
Bicarbonate	2009	288	288-288	0	NA	ppm	No	Corrosion of carbonate rocks such as limestone			
Calcium	2010	90.6	90.6-90.6	0	NA	ppm	No	Abundant naturally occurring element			
Chloride	2009	17	17-17	0	300	ppm	No	Abundant naturally occurring element; used in voil field activity			
Hardness (as Ca/Mg)	2010	305	305-305	0	300	ppm	No	Naturally occurring calcium and magnesium			
Magnesium	2010	19.1	19.1-19.1	0	NA	ppm	No	Abundant naturally occurring element			
Nickel	2010	0.00255	0.00255- 0.00255	0	NA	ppm	No	Erosion of natural deposits			
рН	2009	7.0	7.0-7.0	>7.0	>7.0	units	No	Measure of corrosively of water			
Sodium	2010	10.2	10.2-10.2	0	NA	ppm	No	Erosion of natural occurring element			
Sulfate	2009	45	45-45	0	300	ppm	No	Naturally occurring; common industrial byprodu			
Total alkalinity (as $CaCO_3$ )	2009	236	236-236	0	NA	ppm	No	Naturally occurring soluble mineral salts			
Total dissolved solids	2009	329	329-329	0	1,000	ppm	No	Total dissolved mineral constituents in water			
Zinc	2010	0.00553	0.00553-0.00553	0	5	ppm	No	Moderately abundant naturally occurring elemer			

# **DISINFECTANTS AND DISINFECTION BY-PRODUCTS**

Constituent	Collection Date	Highest Level Detected	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination
Haloacetic acids (HAAs)	2010	2.2	2.2-2.2	0	60	ppb	No	By-product of drinking water chlorination
Total Trihalomethanes (TThm)	2010	11.9	11.9–11.9	0	80	ppb	No	By-product of drinking water chlorination

# **INORGANIC CONTAMINANTS**

Constituent	Collection Date	Highest Level Detected	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination
Barium	2010	0.0367	0.0367-0.0367	0	2	ppm	No	Discharge of drilling wastes; discharge from metal ref
Fluoride	2009	0.19	0.19-0.19	0	4.0	ppm	No	Erosion of natural deposits; water additive which discharge from fertilizer and aluminum factories
Nitrate (measured as nitrogen)	2011	0.675	0.675-0.675	0	10	ppm	No	Runoff from fertilizer use; leaching from septic tanks,

# **RADIOACTIVE CONTAMINANTS**

Constituent	Collection Date	Highest Level Detected	Range of Levels Detected	MCLG	MCL	Units	Violation	Likely Source of Contamination
Gross beta particles	2010	<4.0	<4.0-<4.0	0	50	pCi/L	No	Decay of natural and man-made deposits
Gross alpha	2010	<2.0	<2.0-<2.0	0	15	pCi/L	No	Erosion of natural deposits
				c c 1 .				

Note: The MCL for beta particles is 4 mrem/year. EPA considers 50 pCi/L to be the level of concern for beta particles.

preservatives; corrosion of

ion of natural deposits

n water purification; byproduct of

duct; byproduct of oil field activity

ent; used in the metal industry

refineries; erosion of natural deposits ch promotes strong teeth;

s, sewage; erosion of natural deposits

# **CONTACT US**

#### **Questions About Your** Water Quality Report?

If you would like more information or a copy of this Water Quality Report, call:

210-233-3176

#### Call 24 Hours a Day to:

- Report leaks, main breaks, or sewer back-ups
- Discuss water quality concerns
- 210-704-SAWS (210-704-7297)

# In Your Neighborhood

SAWS External Relations team extends its community outreach efforts with neighborhood leaders through homeowners associations and neighborhood meetings, schools and community gatherings. Call us for more information about how we can assist in your neighborhood.

#### 210-233-3246

#### Website

Our website has the latest news and program information on water issues.

www.saws.org

#### En Español

Este informe incluye información importante sobre el aqua potable. Si tiene preguntas o comentarios sobre éste informe en español, favor de llamar al

#### 210-233-3176

Para hablar con una persona bilingüe en español.



**NORTH SAN ANTONIO HILLS** PWS ID Number: TX0150205