

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
 FOR: Fire Hydrant Repair Parts
 TIME & DATE: (Date of Award through September 30, 2009)
 3:00 p.m., October 3, 2007

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	UNIT	PRICE	TOTAL	HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P. O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Millam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
	GROUP 1 - American Darling Fire Hydrant Parts			*							
1.	20 set Bolt & nut set, barrel, material plated steel, used for 5 1/4", 8 each/set, Model B62B, Part 54-62-39-7	UNIT PRICE TOTAL	59.76 1,195.20		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
2.	15 ea. bolt & nut set, base, material rustproof steel, used for 5 1/4" Model B62B, Part 54-62-39	UNIT PRICE TOTAL	4.48 67.20		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
3.	20 ea. coupling, breakable rod, material gray iron, used for 5 1/4" Brand B62B, Part #54-62-29-30	UNIT PRICE TOTAL	33.18 663.60		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
4.	30 set Coupling, cotter pins, size 8" x 15", Range A 8.50-9.37, material stainless steel used for 5 1/4" & 6", 2 each set Brand B62B, Part #54-62-29-31	UNIT PRICE TOTAL	7.46 223.80		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
5.	2 ea. Coupling, rod, material cast iron, used for 5" brand B50E	UNIT PRICE TOTAL	29.13 58.26		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
6.	5 ea. Cover, housing, used for gray iron, brand B-62-B, part #62-5	UNIT PRICE TOTAL	32.87 164.35		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
7.	25 ea. Flange, breakable, material cast iron, used for 5-1/4", brand B-84-B Part# 84-29-15	UNIT PRICE TOTAL	29.13 728.25		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
8.	2 ea. Flange, breakable, material gray iron, used for 5-1/4", brand B-62-I Part #62-29-15	UNIT PRICE TOTAL	32.12 64.24		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
9.	15 ea. Gasket, barrel, material composition rubber, used for 6", Model B84B Part #60-84-38-1	UNIT PRICE TOTAL	4.25 63.75		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
10.	15 ea. Gasket, barrel, material composition rubber, used for 5-1/4", Model B62B Part #54-62-38-1	UNIT PRICE TOTAL	4.25 63.75		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
11.	2 ea. Gasket, barrel, material rubber, used for 5", Model B50B, Part #50-29-2f	UNIT PRICE TOTAL	11.11 22.22		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
12.	5 ea. Gasket, cover, material fiber, used for 5-1/4", Model B-84-B, Part #54-84-1f	UNIT PRICE TOTAL	4.25 21.25		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
13.	10 set Gasket, drain ring, material composition rubber, used for 5-1/4", 2 each/set Model B-84-B, Part #84-38	UNIT PRICE TOTAL	7.93 79.30		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
14.	2 ea. Gasket, drain ring, used for 5", model B-50-E	UNIT PRICE TOTAL	4.76 9.52		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
15.	5 ea. Gasket, housing, material composition rubber, used for 5-1/4", Model B-84-B, Part #6-84-14	UNIT PRICE TOTAL	3.98 19.90		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
16.	2 ea. Gasket, seat, used for 5", Model B-50-B	UNIT PRICE TOTAL	17.46 34.92		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
17.	5 ea. Gasket, steamer, material rubber, used for 5-1/4", Model B-84-B, Part#6-84-2	UNIT PRICE TOTAL	4.25 21.25		No Bid	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE

SAN ANTONIO WATER SYSTEM
P. O. BOX 2449
SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
FOR: Fire Hydrant Repair Parts
TIME & DATE: (Date of Award through September 30, 2009)
3:00 p.m., October 3, 2007
ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	UNIT PRICE	HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P. O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Millam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
18.	30 ea. Kit, breakaway 1985 and old, used for 5-1/4" includes 8 bolts, Model B62E	UNIT PRICE TOTAL	147.05 4,411.50	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
19.	3 ea. Kit, extension, size 12", used for 5 1/4", Model B62B	UNIT PRICE TOTAL	221.96 665.88	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
20.	30 ea. Kit, extension, size 12", used for 5 1/4", Model B84B-25C	UNIT PRICE TOTAL	183.81 5,514.30	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
21.	20 ea. Kit, extension, size 6", used for 5 1/4", Model B84B-25C	UNIT PRICE TOTAL	132.60 2,652.00	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
22.	80 ea. Kit, fire hydrant, traffic, used for 5 1/4", includes 8 bolts, Model B84B-25C	UNIT PRICE TOTAL	90.60 7,248.00	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
23.	25 ea. Kit, traffic repair quick fix, used for 5 1/4", includes flange, Model B62B Part #B55204-KIT	UNIT PRICE TOTAL	137.31 3,432.75	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
24.	10 ea. Lever, drain, used for 5 1/4", Model B84B, Part #84-31	UNIT PRICE TOTAL	83.34 833.40	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
25.	5 ea. Lever, drain, used for 6", Model B84B, Part #1205	UNIT PRICE TOTAL	92.08 460.40	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
26.	10 ea. Nut, operating, material bronze B763, Alloy 844, used for 5 1/4", Model B84B, Part #54-84-1	UNIT PRICE TOTAL	109.54 1,095.40	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
27.	2 ea. Nut, segment bolt, used for 5", Model B-50-E	UNIT PRICE TOTAL	3.96 7.92	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
28.	5 ea. Nut, travel stop, used for 5 1/4", Model B84B, Part #84-30-0f	UNIT PRICE TOTAL	15.88 79.40	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
29.	40 ea. Overhaul kit, fire hydrant, used for fire hydrant repair, Model B-84-B MFG Part #03KIT 1 051	UNIT PRICE TOTAL	109.69 4,387.60	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
30.	45 ea. Overhaul kit, fire hydrant, size 5 1/4", Model B-62-B N.S., Mfg Part #03KIT 1 05f	UNIT PRICE TOTAL	99.13 4,460.85	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
31.	30 ea. Overhaul kit, fire hydrant, size 5 1/4", Model B-62-B O.S., Mfg. Part #03KIT 1 05f	UNIT PRICE TOTAL	99.13 2,973.90	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
32.	45 ea. Overhaul kit, free hydrant, size 5 1/4", Model B-84-B, Mfg. Part #03KIT 1 05	UNIT PRICE TOTAL	109.69 4,936.05	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
33.	5 ea. Pin, coupling, kit used for 5", Model B-50-B, A-159621-5 H525 62/H600 84 F/1-1/4 SQ	UNIT PRICE TOTAL	4.25 21.25	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
34.	5 ea. Pin, rod coupling, used for 5", Model B-50-B	UNIT PRICE TOTAL	4.25 21.25	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
35.	1 ea. O-Ring cover, material Buna N, used for 5 1/4", Model B-84-B, Part #6-84-2-	UNIT PRICE TOTAL	4.25	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE
36.	1 ea. O-Ring drain, material bronze, used for 5 1/4", Model B62B, Part #54-62-3f	UNIT PRICE TOTAL	182.56	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
 FOR: Fire Hydrant Repair Parts
 TIME & DATE: (Date of Award through September 30, 2009)
 3:00 p.m., October 3, 2007

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	UNIT	PRICE	STATUS	STATUS	STATUS	STATUS	STATUS	STATUS	
				HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P. O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Millam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
37.	5 ea. O-Ring, drain, material bronze, used for 5 1/4", Model B-84-B, Part #6-84-3.	UNIT PRICE TOTAL	175.38 876.90	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
38.	5 ea. O-Ring housing, material Buna N, used for 5 1/4", Model B-84-B, Part #6-84-2.	UNIT PRICE TOTAL	4.25 21.25	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
39.	2 ea. O-Ring inside seat, material Buna N, used for 5 1/4", Model B62B, Part #54-62-36.	UNIT PRICE TOTAL	7.94 15.88	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
40.	35 ea. O-Ring nozzle, used for 5 1/4", Model B84B, Part #84-20-4	UNIT PRICE TOTAL	4.25 148.75	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
41.	5 ea. O-Ring seat, material Buna N, used for 5 1/4", Model B-84-E	UNIT PRICE TOTAL	7.94 39.70	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
42.	5 ea. O-Ring seat, material Buna N, used for 6", Model B-84-t	UNIT PRICE TOTAL	11.11 55.55	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
43.	5 ea. Screw, pipe, material stal, used for 5 1/4", Model B62B, Part #54-62-5.	UNIT PRICE TOTAL	3.18 15.90	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
44.	20 ea. Seal, hydrant seat, material bronze, used for 5 1/4", Model B-84-B, Part #84-35-0.	UNIT PRICE TOTAL	140.25 2,805.00	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
45.	30 ea. Seat, hydrant, material bronze, used for 5 1/4", Model B62B, Part #62-35-0F	UNIT PRICE TOTAL	144.50 4,335.00	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
46.	10 ea. Seat, hydrant, material bronze B763 Alloy844, used for 6", Model B84B, Part #60-84-35-0.	UNIT PRICE TOTAL	144.46 1,444.60	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
47.	2 ea. Valve, bottom, material cast iron, used for 6", Model B-84-B, Part #6-84-4.	UNIT PRICE TOTAL	56.35 112.70	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
48.	15 ea. Valve, hydrant, material rubber, used for 5 1/4", Model B62B, Part #54-62-4	UNIT PRICE TOTAL	47.63 714.45	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
49.	5 ea. Valve, hydrant, material rubber, used for 6", Model B84B, Part #60-84-4	UNIT PRICE TOTAL	55.56 277.80	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
50.	2 ea. Valve, main, used for 5 1/4", Model B84B, Part #B56637	UNIT PRICE TOTAL	47.63 95.26	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
51.	20 ea. Washer, thrust, material nylatron, used for 5 1/4", Model B62B, Part #54-62-4-4	UNIT PRICE TOTAL	4.76 95.20	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
	TOTAL GROUP 1	TOTAL	* 57,943.36	No Bid	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
	GROUP 2 - Clow Fire Hydrant Parts			*						
1.	10 ea. Bearing, operating nut thrust, used for 5 1/4", brand medallion, Part #M-1.	UNIT PRICE TOTAL	1.01 10.10	1.08 10.80	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	
2.	2 ea. Bolt & Nut set, safety flange, material zinc plated steel, used for 5 1/4", brand medallion Part #M-46	UNIT PRICE TOTAL	1.15 2.30	10.45 20.90	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	
3.	2 ea. Cap, weather, material cast iron, used for 5 1/4", brand medallion, Part#M-2t	UNIT PRICE TOTAL	19.08 38.16	20.25 40.50	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	
4.	20 ea. Coupling, safety stem, material steel tubing used for 5 1/4", brand Medallion, Part #M-10/M-220-2349	UNIT PRICE TOTAL	23.24 464.80	24.69 493.80	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	

SAN ANTONIO WATER SYSTEM
P. O. BOX 2449
SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
FOR: Fire Hydrant Repair Parts
TIME & DATE: (Date of Award through September 30, 2009)
3:00 p.m., October 3, 2007
ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	UNIT	HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P. O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Millam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
5.	7 ea. Facing, drain valve, material rubber, used for 5 1/4", Model Medallion, Part #M-16/T160080	UNIT PRICE TOTAL	3.31 23.17	3.75 26.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
6.	5 set Flange, safety, material ductile iron, used for 5 1/4", Brand Medallion, Part #M-46/I-160-080	UNIT PRICE TOTAL	177.14 885.70	177.22 886.10	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
7.	100 ea. Kit, breakaway, size 5 1/4", used for breakflange repair, Model F2500, Part #R162054	UNIT PRICE TOTAL	98.64 9,864.00	90.47 9,047.00	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
8.	50 ea. Kit, extension, size 12", used for 5 1/4", Model Medallion, Part #R1620665	UNIT PRICE TOTAL	238.59 11,929.50	244.65 12,232.50	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
9.	15 ea. Kit, extension, size 6", used for 5 1/4", Model Medallion, Part #R1620664	UNIT PRICE TOTAL	201.88 3,028.20	209.53 3,142.95	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
10.	75 ea. Kit, safety flange, used for 5 1/4", Model Medallion, Part #R1620653	UNIT PRICE TOTAL	98.76 7,407.00	90.47 6,785.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
11.	2 ea. Nut, operating, material bronze, used for 5 1/4", Model Medallion, Part #M-3	UNIT PRICE TOTAL	65.19 130.38	65.22 130.44	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
12.	2 ea. Nut, thrust o-ring, material NBR, used for 5 1/4", Model Medallion, Part #M-28	UNIT PRICE TOTAL	0.51 1.02	0.55 1.10	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
13.	2 ea. Nut, thrust setscrew, material stainless steel, used for 5 1/4", Model Medallion, Part #M-53	UNIT PRICE TOTAL	1.11 2.22	1.20 2.40	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
14.	125 ea. Overhaul kit, fire hydrant, size 5 1/4", Model Medallion, 02KIT, 1 05	UNIT PRICE TOTAL	90.24 11,280.00	45.37 5,671.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
15.	5 ea. Pin, drain valve facing, material stainless steel, used for 5 1/4", Model Medallion, Part #M-1	UNIT PRICE TOTAL	0.41 2.05	0.45 2.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
16.	5 ea. Pin, safety coupling, material stainless steel, used for 5 1/4", Model Medallion Part, #M-11/T0400891	UNIT PRICE TOTAL	2.21 11.05	2.36 11.80	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
17.	5 ea. Pin, safety coupling cotter, material stainless steel, used for 5 1/4", Model Medallion Part #M-9	UNIT PRICE TOTAL	0.61 3.05	0.66 3.30	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
18.	5 ea. Pin, upper stem, material stainless steel, used for 5 1/4", Model Medallion, Part #M-8	UNIT PRICE TOTAL	4.33 21.65	4.62 23.10	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
19.	2 ea. O-Ring, drain, material bronze, used for 5 1/4", Model Medallion, Part #M-54	UNIT PRICE TOTAL	105.44 210.88	107.50 215.00	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
20.	5 ea. O-Ring, drain, material N B R, used for 5 1/4", Model Medallion, Part #M-53	UNIT PRICE TOTAL	1.61 8.05	1.72 8.60	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
21.	5 ea. O-Ring, operating nut, used for 5 1/4", Model Medallion, Part #M-1/T-240-0813	UNIT PRICE TOTAL	3.61 18.05	3.85 19.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
22.	25 ea. O-Ring, seat lower, used for 5 1/4", Model Medallion, Part #M-20/T-240-1318	UNIT PRICE TOTAL	3.41 85.25	3.64 91.00	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
23.	15 ea. O-Ring, safety flange, material N B R, used for 5 1/4", Model Medallion, Part #M-4	UNIT PRICE TOTAL	1.71 25.65	1.83 27.45	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
24.	100 ea. O-Ring, seat, material bronze, used for 5 1/4", Model Medallion, Part #M-19/F-1600803	UNIT PRICE TOTAL	75.39 7,539.00	75.43 7,543.00	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
 FOR: Fire Hydrant Repair Parts
 TIME & DATE: (Date of Award through September 30, 2009)
 3:00 p.m., October 3, 2007
 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	UNIT	HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P.O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Millam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
25.	60 ea. O-Ring, seat upper, material NBR, used for 5 1/4", Model Medallion, Part #M-18/T-240-072.	UNIT PRICE TOTAL	4.93 295.80	5.25 315.00	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
26.	5 ea. O-Ring, stem, material NBR used for 5 1/4", Model Medallion, Part #M-31	UNIT PRICE TOTAL	0.41 2.05	0.45 2.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
27.	10 ea. Screw, cap hold down, material zinc plated steel used for 5 1/4", Model Medallion Part #M-25/T-040-0890	UNIT PRICE TOTAL	0.41 4.10	0.45 4.50	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
28.	10 ea. Stem, upper, used for 5 1/4", Brand Medallion, Part #M-7	UNIT PRICE TOTAL	74.92 749.20	76.42 764.20	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
29.	7 ea. Valve, lower plate, material brass, used for 5 1/4", Model Medallion, Part #M-24/M160080	UNIT PRICE TOTAL	85.79 600.53	80.27 561.89	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
30.	70 ea. Valve, main, material rubber used for 5 1/4", Model Medallion, Part #M-21/T-160-080	UNIT PRICE TOTAL	30.14 2,109.80	30.15 2,110.50	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
31.	55 ea. Valve, upper plate, material bronze, used for 5 1/4", Model Medallion, Part #M-17/F-160-080	UNIT PRICE TOTAL	98.35 5,409.25	98.40 5,412.00	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
32.	2 ea. Washer, lower valve plate lock, material stainless steel, used for 5 1/4", Model Medallion Part #M-22	UNIT PRICE TOTAL	1.31 2.62	1.40 2.80	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
	TOTAL GROUP 2	TOTAL	62,164.58	* 55,609.13	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE
	GROUP 3 - Mueller Fire Hydrant Parts								
1.	2 ea. Cap, weather, open right, used for 5 1/4", Brand Centurion, Part #A-2/142815	UNIT PRICE TOTAL	* 13.82 27.64	No Bid	INCOMPLETE	No Bid	12.90 25.80	INCOMPLETE	INCOMPLETE
2.	20 ea. Coupling, safety stem, material stainless steel, used for 5 1/4", Brand Centurion, Part #A-25/190351	UNIT PRICE TOTAL	34.28 685.60	No Bid	INCOMPLETE	No Bid	32.00 640.00	INCOMPLETE	INCOMPLETE
3.	20 ea. Flange, safety, used for 5 1/4", Brand Centurion, Part #A-28/175211-1	UNIT PRICE TOTAL	38.02 760.40	No Bid	INCOMPLETE	No Bid	35.50 710.00	INCOMPLETE	INCOMPLETE
4.	55 ea. Flange, safety bolt & nut, used for 5 1/4", Brand Centurion, Part #A-26	UNIT PRICE TOTAL	4.25 233.75	No Bid	INCOMPLETE	No Bid	3.70 203.50	INCOMPLETE	INCOMPLETE
5.	30 ea. Gasket, bonnet, used for 5 1/4", Model Centurion, Part #10/198357	UNIT PRICE TOTAL	8.09 242.70	No Bid	INCOMPLETE	No Bid	7.10 213.00	INCOMPLETE	INCOMPLETE
6.	40 ea. Kit, main repair used for 5 1/4", Model improved	UNIT PRICE TOTAL	313.61 12,544.40	No Bid	INCOMPLETE	No Bid	293.20 11,728.00	INCOMPLETE	INCOMPLETE
7.	150 ea. Kit, safety flange repair used for 5 1/4", Model Centurions & improved NS, Part #A30	UNIT PRICE TOTAL	102.49 15,373.50	No Bid	INCOMPLETE	No Bid	105.40 15,810.00	INCOMPLETE	INCOMPLETE
8.	2 ea. Nut, hold down used for 5 1/4", Model Centurion, Part #A-4	UNIT PRICE TOTAL	28.71 57.42	No Bid	INCOMPLETE	No Bid	26.80 53.60	INCOMPLETE	INCOMPLETE
9.	10 ea. Nut, operating, used for 5 1/4", Brand open right/1988 or later, Model Centurion, Part#A-1/147814	UNIT PRICE TOTAL	90.36 903.60	No Bid	INCOMPLETE	No Bid	84.50 845.00	INCOMPLETE	INCOMPLETE
10.	1 ea. Nut, operating weather cap, used for 5 1/4", Model 107, Part #H-11	UNIT PRICE TOTAL	44.45	No Bid	INCOMPLETE	No Bid	41.50	INCOMPLETE	INCOMPLETE

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
 FOR: Fire Hydrant Repair Parts
 TIME & DATE: (Date of Award through September 30, 2009)
 3:00 p.m., October 3, 2007
 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	UNIT PRICE	TOTAL	HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P. O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Milam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
11.	100 ea. Overhaul Kit, size 5 1/4", Model Centurion, Part #01KIT 1 05.	UNIT PRICE	75.56	No Bid	INCOMPLETE	No Bid	77.40	INCOMPLETE	INCOMPLETE	
		TOTAL	7,556.00				7,740.00			
12.	25 ea. Pin, Clevis, used for 5 1/4", Model centurion, Part #A-30/195235	UNIT PRICE	5.21	No Bid	INCOMPLETE	No Bid	4.50	INCOMPLETE	INCOMPLETE	
		TOTAL	130.25				112.50			
13.	35 ea. Pin, Cotter, used for 5 1/4", Model Centurion, Part #A-29	UNIT PRICE	0.83	No Bid	INCOMPLETE	No Bid	0.73	INCOMPLETE	INCOMPLETE	
		TOTAL	29.05				25.55			
14.	1 ea. Pin, Screw, used for 5 1/4", Model 107, Part #H-111	UNIT PRICE		No Bid	INCOMPLETE	No Bid		INCOMPLETE	INCOMPLETE	
		TOTAL	24.56				21.60			
15.	1 ea. Pin, Stem, used for 5 1/4", Model Centurion, Part #A-33/195347	UNIT PRICE		No Bid	INCOMPLETE	No Bid		INCOMPLETE	INCOMPLETE	
		TOTAL	4.24				3.73			
16.	5 ea. Plug, Oil Filler, used for 5 1/4", Model Centurion, Part #A-7	UNIT PRICE	2.13	No Bid	INCOMPLETE	No Bid	1.73	INCOMPLETE	INCOMPLETE	
		TOTAL	10.65				8.65			
17.	5 ea. O-Ring, Bonnet, used for 5 1/4", Model Centurion, Part #A-5	UNIT PRICE	3.78	No Bid	INCOMPLETE	No Bid	3.33	INCOMPLETE	INCOMPLETE	
		TOTAL	18.90				16.65			
18.	25 ea. O-Ring, Bottom Seat, used for 5 1/4", Model Centurion, Part #A-44/142895	UNIT PRICE	3.78	No Bid	INCOMPLETE	No Bid	3.33	INCOMPLETE	INCOMPLETE	
		TOTAL	94.50				83.25			
19.	20 ea. O-Ring, top seat, used for 5 1/4", Model Centurion, Part #A-39-195033	UNIT PRICE	3.78	No Bid	INCOMPLETE	No Bid	3.33	INCOMPLETE	INCOMPLETE	
		TOTAL	75.60				66.60			
20.	60 ea. Ring, seat, material bronze, used for 5 1/4", Model Centurion, Part A-43/142764	UNIT PRICE	125.68	No Bid	INCOMPLETE	No Bid	117.50	INCOMPLETE	INCOMPLETE	
		TOTAL	7,540.80				7,050.00			
21.	1 ea. Screw, drain valve, used for 5 1/4", Model Standard, Part #14	UNIT PRICE		No Bid	INCOMPLETE	No Bid		INCOMPLETE	INCOMPLETE	
		TOTAL	0.83				0.73			
22.	20 ea. Valve, Main, material rubber, used for 5 1/4", Model Centurion, Part #A-45/192911	UNIT PRICE	45.12	No Bid	INCOMPLETE	No Bid	66.10	INCOMPLETE	INCOMPLETE	
		TOTAL	902.40				1,322.00			
23.	35 ea. Valve, upper plate, material bronze, used for 5 1/4", Model Centurion, Part, #A-36/184051	UNIT PRICE	86.73	No Bid	INCOMPLETE	No Bid	81.10	INCOMPLETE	INCOMPLETE	
		TOTAL	3,035.55				2,838.50			
	TOTAL GROUP 3	TOTAL	50,296.79	No Bid	INCOMPLETE	No Bid	49,560.16	INCOMPLETE	INCOMPLETE	
	GROUP 4 - M&H FIRE HYDRANT PARTS									
1.	15 ea. Kit, breakaway, used for 5 1/4", Model 125	UNIT PRICE	99.63	No Bid	INCOMPLETE	No Bid	No Bid	75.50	79.63	
		TOTAL	1,494.45					1,132.50	1,194.45	
2.	2 ea. O-Ring, weatherproof, material rubber, used for 5 1/4", Model 129, Part #30	UNIT PRICE	5.09	No Bid	INCOMPLETE	No Bid	No Bid	2.31	3.25	
		TOTAL	10.18					4.62	6.50	
	TOTAL GROUP 4	TOTAL	1,504.63	No Bid	INCOMPLETE	No Bid	No Bid	1,137.12	1,200.95	
	GROUP 5 - U.S. PIPE FIRE HYDRANT PARTS									
1.	2 ea. Facing, drain valve, material rubber, used for 5 1/4", Year 1994 and on, Metropolitan 250 M-94 Part #39	UNIT PRICE	5.63	No Bid	4.50	6.08	No Bid	No Bid	INCOMPLETE	
		TOTAL	11.26		9.00	12.16				
2.	5 ea. Gasket, standpipe ring, used for 5 1/4", Model H-205, Part #HR65	UNIT PRICE	15.31	No Bid	22.80	30.78	No Bid	No Bid	INCOMPLETE	
		TOTAL	76.55		114.00	153.90				

SAN ANTONIO WATER SYSTEM
P. O. BOX 2449
SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
FOR: Fire Hydrant Repair Parts
TIME & DATE: (Date of Award through September 30, 2009)
3:00 p.m., October 3, 2007
ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	UNIT	PRICE	TOTAL	HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P. O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Millam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
3.	5 ea. Kit, extension, size 12", used for 5 1/4", Model 250, Part #M94	UNIT PRICE TOTAL	225.00 No Bid 1,125.00	309.00 1,545.00	309.00 1,545.00	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
4.	20 ea. Kit, traffic repair, used for 5 1/4" fire hydrant, Brand Metropolitan, Model 250 M-94 (Yr. 94 & after), Part #658665	UNIT PRICE TOTAL	93.38 No Bid 1867.6	114.00 2,280.00	153.90 3,078.00	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
5.	5 ea. Nut, operating, material cast iron, used for 5 1/4", Model sentinel, Part #1	UNIT PRICE TOTAL	34.69 No Bid 173.45	27.75 138.75	28.89 144.45	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
6.	25 ea. Overhaul, kit, size 5 1/4", Model Metropolitan 250, Part #07KIT 1 525 05:	UNIT PRICE TOTAL	106.56 No Bid 2664	380.00 9,500.00	513.00 12,825.00	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
7.	2 ea. Pin, top plate, material steel (shear proof), used for 5 1/4", Brand Year 1994 and on, Model Metropolitan 250 M-94, Part #34	UNIT PRICE TOTAL	5.19 No Bid 10.38	4.15 8.30	5.60 11.20	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
8.	2 ea. Ring, seat, material bronze, used for 5 1/4", Brand Year 1994 and on, Model Metropolita 250 M-94, Part #42	UNIT PRICE TOTAL	175.88 No Bid 351.76	149.50 299.00	201.83 403.66	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
9.	5 ea. O-Ring, seat, material rubber, used for 5 1/4", Brand Year 1994 and on Model Metropolita 250 M-94, Part #43	UNIT PRICE TOTAL	9.00 No Bid 45.00	7.20 36.00	9.72 48.60	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
10.	2 ea. Screw, hold down nut, material stainless steel, used for 5 1/4", Model Sentinel, Part #:	UNIT PRICE TOTAL	3.09 No Bid 6.18	2.05 4.10	35.84 71.68	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
11.	5 ea. Valve, main, material rubber, used for 5 1/4" Yar 1994 and on, Model Metropolitan 250 M-94 Part #44	UNIT PRICE TOTAL	45.13 No Bid 225.65	36.10 180.50	48.74 243.70	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
12.	5 ea. Valve, main, material rubber Buna-S, used for 5 1/4", Model H-205 USP hydrant, Part #H-4	UNIT PRICE TOTAL	50.00 No Bid 250.00	86.75 433.75	117.11 585.55	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
13.	5 ea. Valve, upper plate, material bronze, used for 5 1/4" Year 1994 and on, Model Metropolita 250 M-94, Part #35	UNIT PRICE TOTAL	1.63 No Bid 8.15	130.00 650.00	175.50 877.50	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
	TOTAL GROUP 5	TOTAL	* 6,814.98	15,198.40	20,000.40	No Bid	No Bid	No Bid	No Bid	INCOMPLETE	
	GROUP 6 - Kennedy Fire Hydrant Parts	UNIT	*								
1.	10 ea. Coupling, stem break, material cast iron, used for 5 1/4", Brand K84A, Part #K811	PRICE TOTAL	41.11 411.10	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	INCOMPLETE		
2.	5 ea. Coupling, stem break, used for 5 1/4", Brand K11, Part #K1121	UNIT PRICE TOTAL	44.05 No Bid 220.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	INCOMPLETE		
3.	2 ea. Facing, drain valve, material Buna N, used for 5 1/4", Model K81A, Part #K813	UNIT PRICE TOTAL	9.19 No Bid 18.38	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	INCOMPLETE		
4.	5 ea. Gasket, seat ring, material copper asbestos, used for 5 1/4", Model K11, Part #K113:	UNIT PRICE TOTAL	12.01 No Bid 60.05	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	INCOMPLETE		
5.	5 ea. Gasket, standpipe, used for 5 1/4", Model K11, Part #K1124	UNIT PRICE TOTAL	10.25 No Bid 51.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	INCOMPLETE		
6.	125 ea. Kit, collision, used for 5 1/4", Model K81A, Part #K-8149/1585C00R1X81Z	UNIT PRICE TOTAL	103.45 No Bid 12,931.25	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	INCOMPLETE		
7.	15 ea. Kit, extension, size 12", Model K81A	UNIT PRICE TOTAL	202.39 No Bid 3,035.85	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	INCOMPLETE		
8.	1 ea. Kit, extension, size 6", Model K81A	UNIT PRICE TOTAL	205.53	INCOMPLETE	No Bid	No Bid	No Bid	INCOMPLETE	INCOMPLETE		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
 FOR: Fire Hydrant Repair Parts
 TIME & DATE: (Date of Award through September 30, 2009)
 3:00 p.m., October 3, 2007
 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	UNIT PRICE TOTAL	HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P. O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Milam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
9.	5 ea. Nozzle, remover tool, size 2 1/2" wrench hose, used for 5 1/4", Brand K81A, Part #K-8148/331037	UNIT PRICE 56.63 TOTAL 283.15		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
10.	1 ea. Nut, operating stem, material bronze, used for 5 1/4", Model K81A, Part #K810	UNIT PRICE 92.36 TOTAL		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
11.	60 ea. Overhaul kit, size 5 1/4", Model guardian K81A, Part #05KIT 1 05	UNIT PRICE 88.64 TOTAL 5,318.40		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
12.	5 ea. Pin, cotter, material stainless steel, used for 5 1/4", Mode K81A, Part #K-8117/443010	UNIT PRICE 1.39 TOTAL 6.95		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
13.	10 ea. Pin, drain valve, material steel, used for 5 1/4", Model K81, Part #K813	UNIT PRICE 7.14 TOTAL 71.40		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
14.	20 ea. O-Ring, lower, material Buna N, used for 5 1/4", Model Guardian, Part #K813	UNIT PRICE 4.85 TOTAL 97.00		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
15.	5 ea. O-Ring, material Buna N, used for 5 1/4", Model K81A, Part #K811	UNIT PRICE 3.46 TOTAL 17.30		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
16.	15 ea. O-Ring, material Buna N, used for 5 1/4", Model K81A, Part #K8126/	UNIT PRICE 4.85 TOTAL 72.75		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
17.	10 ea. Ring, seat, material bronze, used for 5 1/4", Model K11, Part #K113	UNIT PRICE 134.01 TOTAL 1,340.10		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
18.	30 ea. Ring, seat, material bronze, used for 5 1/4", Model K81A, Part #K812	UNIT PRICE 120.56 TOTAL 3,616.80		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
19.	15 set Ring, standpipe breaking (2 Per), material cast iron, used for 5 1/4", Model Guardian K81A, Part #K8119	UNIT PRICE 24.01 TOTAL 360.15		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
20.	10 ea. O-Ring, weather seal, material Buna N, used for 5 1/4", Model K11, Part #K110	UNIT PRICE 13.00 TOTAL 130.00		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
21.	15 ea. Valve, main, material neoprene, used for 5 1/4", Model K81, Part #K813	UNIT PRICE 74.68 TOTAL 1,120.20		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
22.	10 ea. Valve, drain, material bronze, used for 5 1/4", Model K81A, Part #K813	UNIT PRICE 83.88 TOTAL 838.80		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
23.	15 ea. Valve, drain, material bronze, used for 5 1/4", Model K81A, Part #K8136/331614	UNIT PRICE 83.88 TOTAL 1,258.20		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
	TOTAL GROUP 6	TOTAL * 31,557.22		No Bid	INCOMPLETE	No Bid	No Bid	INCOMPLETE	INCOMPLETE
	GROUP 7 - Waterous Fire Hydrant Parts	TOTAL *							
1.	10 ea. Kit, traffic repair, used for 5 1/4", Model Pacer, Part #K528/AFTER June 198	UNIT PRICE 89.38 TOTAL 893.80		No Bid	No Bid	No Bid	No Bid	No Bid	86.15 861.50
2.	1 ea. Pipe, lower standpipe, Brand Pacer	UNIT PRICE 365.63 TOTAL		No Bid	No Bid	No Bid	No Bid	No Bid	344.12
	TOTAL GROUP 7	TOTAL * 1,259.43		No Bid	No Bid	No Bid	No Bid	No Bid	1,205.62

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL: Biennial Contract for
 FOR: Fire Hydrant Repair Parts
 TIME & (Date of Award through September 30, 2009)
 DATE: 3:00 p.m., October 3, 2007
 ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		HD Supply Waterworks 7620 Grissom Rd. San Antonio, TX 78251	Act Pipe & Supply Co. 4719 Dodge St. San Antonio, TX 78217	Empirewest, Inc. P. O. Box 521 Springville, Utah 84663	Morrison Supply Co. 5340 N. Loop 1604 E. San Antonio, TX 78247	Big Country Waterworks Supply, Inc. 2400 Stephen F. Austin Dr. Brownwood, TX 76801	Hydraflo, Inc. 1030 Milam St. Beaumont, TX 77701	Municipal Water Works Supply, LP 6959 State Hwy 276 Royse City, TX 75189
Terms		Net 30 days	Net 30 days	Net 30 days	Net 30 days	Net 30 days	Net 30 days	Net 30 days
Delivery Days		5-20 days	15 days				56 days	10-15 days

***DENOTES LOW BIDDER**

BID INVITATIONS MAILED TO AND/OR PICKED UP BY

Act Pipe & Supply
 American Cast Iron Pipe
 American Darling Valve
 Big Country Waterworks Supply
 Empirewest, Inc
 Ferguson
 HD Supply
 Hydraflo, Inc.
 Kennedy Valve

Metro Service Consultants
 Moore Supply
 Morrison Supply Co.
 Mueller co.
 Municipal Water Works Supply
 PMI Steel Pipe
 Quality Hydrant
 Sheffey & Assoc.
 William Supply Co.

Demandstar
 SAWS website