

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

1.	34th Street Potable Water Ground Storage Tank 5.0 MG; 164.5 feet diam.; 44.3 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	250.00 140.00 375.00 4,100.00 125.00 4,990.00	BID NOT TABULATED INCOMPLETE BID		
2.	Avenue B Reuse Water Ground Storage Tank 0.40 MG; 54 feet diam.; 28.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL	250.00 140.00 375.00 1,740.00 125.00 1,850.00 4,480.00			
3.	Braun Potable Water Standpipe Tank 0.72 MG; 32.5 feet diam.; 125.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	275.00 140.00 375.00 1,680.00 125.00 2,595.00			
4.	Callaghan Potable Water Elevated Tank 1.00 MG; 91.3 feet diam.; 39.0 feet bowl height; 112.5 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not-drained) Cleaning cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	250.00 140.00 375.00 1,320.00 125.00 2,210.00			
5.	Cedar Creek Potable Water Hydro-pneumatic Tank 0.01 MG; 6.0 feet diam.; 22 inches Water/Level Tank; 6.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation TOTAL	180.00 80.00 260.00			

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
11.	Dos Rios Reuse Water Hydro-pneumatic Tank 2.0 MG; 10 feet diam.; 6.5 feet Water Level Tank; 40 feet length Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		280.00 2,520.00	BID NOT TABULATED INCOMPLETE BID	
12.	Helotes Potable Water Ground Storage Tank 5.0 MG; 150.0 feet diam.; 41.8 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 4,430.00		
13.	Helotes Park #3 Potable Water Standpipe Tank 0.27 MG; 21.5 feet diam.; 102.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		265.00 2,115.00		
14.	Pinn Road Reuse Water Ground Storage Tank 2.80 MG; 84.0 feet diam.; 80.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		265.00 4,535.00		
15.	Sunset Potable Water Ground Storage Tank 5.0 MG; 110.0 feet diam.; 78.9 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 4,990.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
16.	University Potable Water Ground Storage Tank 5.0 MG, 165.0 feet diam.; 35 feet bowl height; 97.0 feet column height; 135 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 375.00 4,100.00 125.00 4,990.00	BID NOT TABULATED INCOMPLETE BID	
17.	Minor Repairs (Item F) 40.0 Hours Hourly Rate TOTAL		250.00 10,000.00		
18.	Emergency Services (Item E) 4 each Mobilization 60.0 hours Hourly Rate TOTAL		1,200.00 4,800.00 310.00 18,600.00 23,400.00		
	TOTAL AMOUNT FOR YEAR 2010 (ITEMS 1-18)		91,965.00		
1.	OPTION YEAR 1 Artesia Potable Water Ground Storage Tank 5.0 MG; 164.5 feet diam.; 42.3 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 150.00 400.00 4,240.00 125.00 5,165.00		
2.	Basin Potable Water Ground Storage Tank 5.0 MG; 165.0 feet diam.; 38.3 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 150.00 400.00 4,240.00 125.00 5,165.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

3.	Brooks Reuse Water Ground Storage Tank 0.50 MG; 54.0 feet diam.; 27.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		250.00 140.00 400.00 1,980.00 125.00 1,250.00 4,145.00	BID NOT TABULATED INCOMPLETE BID		
4.	Culebra Potable Water Ground Storage Tank #1 0.05 MG; 17.0 feet diam.; 32.5 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 400.00 895.00 125.00 1,810.00			
5.	Culebra Potable Water Ground Storage Tank #2 0.05 MG; 17.0 feet diam.; 32.5 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 400.00 895.00 125.00 1,810.00			
6.	Culebra Potable Water Hydro-Pneumatic Tank 0.01 MG; 10 feet diam.; 6.0 feet Water Level Tank; 20 feet length Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation TOTAL		195.00 140.00 335.00			
7.	Devine Reuse Water Elevated Storage Tank 1.20 MG; 84 feet diam.; 43 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		250.00 140.00 400.00 2,840.00 125.00 2,250.00 6,005.00			

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & DATE: (Date of Award through December 31, 2010)
 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

8.	East Houston Reuse Water Ground Storage Tank 1.0 MG; 75 feet diam.; 32 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 400.00 1,840.00 125.00 2,755.00	BID NOT TABULATED INCOMPLETE BID		
9.	Fredericksburg Reuse Water Elevated Storage Tank 1.0 MG; 74 feet diam.; 135 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		250.00 140.00 400.00 1,440.00 125.00 1,850.00 4,205.00			
10.	Hidden Springs Potable Water Hydro-Pneumatic Tank #1 6700 MG; 6 feet diam.; 56 feet overall length Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation TOTAL		240.00 140.00 380.00			
11.	Hidden Springs Potable Water Hydro-Pneumatic Tank #2 6700 MG; 6 feet diam.; 56 feet overall length Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation TOTAL		240.00 140.00 380.00			
12.	Hills Potable Water Ground Storage Tank 3.0 MG; 90 feet diam; 64 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 400.00 2,480.00 125.00 3,395.00			

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
13.	Judson Potable Water Elevated Standpipe Storage Tank 0.25 MG; 40 feet diam; feet bowl height; 35 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 400.00 950.00 125.00 1,865.00	BID NOT TABULATED INCOMPLETE BID	
14.	Marshall Potable Water Ground Storage Tank 0.55 MG; 55.0 feet diam.; 32.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 400.00 1,150.00 125.00 2,065.00		
15.	Pearsall Reuse Water Ground Storage Tank RW 2.50 MG; 120.0 feet diam.; 33.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		250.00 140.00 400.00 2,880.00 125.00 3,250.00 7,045.00		
16.	Randolph Potable Water Ground Storage Tank 5.00 MG; 1.65.0 feet diam.; 32.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 400.00 4,480.00 125.00 5,395.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
17.	Sasse Potable Water Ground Storage Tank 2.0 MG; 92.3 feet diam.; 43.8 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	250.00 140.00 400.00 4,940.00 125.00 5,855.00	BID NOT TABULATED INCOMPLETE BID		
18.	Seale Potable Water Ground Storage Tank #2 3.0 MG; 90.0 feet diam.; 64.5 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	250.00 140.00 400.00 5,380.00 125.00 6,295.00			
19.	Stotzer Reuse Water Ground Storage Tank 2.2 MG; 84 feet diam.; 51 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL	250.00 140.00 400.00 5,250.00 125.00 3,250.00 9,415.00			
20.	Walden Heights Potable Water Ground Storage Tank 0.05 MG, 26.0 feet diam.; 16.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	250.00 140.00 400.00 880.00 125.00 1,795.00			

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
21.	Winwood Potable Water Ground Storage Tank 2.0 MG, 84 feet diam.; 48 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		250.00 140.00 400.00 4,940.00 125.00 5,855.00	BID NOT TABULATED INCOMPLETE BID	
22.	Winwood Potable Water Hydro-Pneumatic Tank 3.0 MG, 10 feet diam.; 7.0 feet Water Level Tank; 36 feet length Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation TOTAL		220.00 140.00 360.00		
23.	Minor Repairs (Item F) Hourly Rate for 40 hours TOTAL		275.00 11,000.00		
24.	Emergency Services (Item E) 4 ea. Mobilization 60 hrs. Hourly Rate TOTAL		1,420.00 5,680.00 320.00 19,200.00 24,880.00		
	TOTAL AMOUNT FOR OPTION YEAR 2011 (ITEMS 1-24)		117,375.00		
1.	OPTION YEAR 2 Avenue B Reuse Water Ground Storage Tank 0.40 MG; 54.0 feet diam.; 28.5 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		275.00 150.00 425.00 1,180.00 140.00 2,150.00 4,320.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

2.	<p>Coliseum Reuse Water Elevated Tank 0.50 MG; 75 feet diam.; 43 feet bowl height; 140 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL</p>	<p>275.00 4,620.00</p>	<p align="center">BID NOT TABULATED INCOMPLETE BID</p>		
3.	<p>Dwyer Potable Water Elevated Standpipe Tank 1.0 MG; 77.0 feet diam.; 41.0 feet Overall Height; Column Height 132 feet Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL</p>	<p>275.00 2,670.00</p>			
4.	<p>Maltsberger Potable Water Ground Storage Tank 7.50 MG; 165.0 feet diam.; 48.0 feet Overall Height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL</p>	<p>275.00 9,910.00</p>			
5.	<p>Menger Potable Water Elevated Standpipe Tank 1.50 MG; 88.0 feet diam.; 46.5 feet bowl height; 116.5 overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL</p>	<p>275.00 3,480.00</p>			

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
	Pinn Rd. Reuse Water Ground Storage Tank 2.80 MG; 84.0 feet diam.; 80.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation			275.00 150.00 425.00 2,595.00 140.00	
6.	TOTAL			3,585.00	
	Ranch Town Potable Water Ground Storage Tank #2 5.00 MG; 165.9 diam.; 32.0 feet Overall Height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation			275.00 150.00 425.00 5,380.00 140.00	
7.	TOTAL			6,370.00	
	Redland Potable Water Elevated Storage Tank 2.50 MG; 105.0 feet diam.; 50.0 feet bowl height; 96.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation			275.00 150.00 425.00 1,970.00 140.00	
8.	TOTAL			2,960.00	
	Woods of Fair Oaks Potable Water Ground Bolted Storage Tank #1 0.097 MG; 26.0 feet diam.; 24.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation			275.00 150.00 425.00 1,180.00 140.00	
9.	TOTAL			2,170.00	

BID NOT TABULATED
INCOMPLETE BID

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
	Woods of Fair Oaks Potable Water Ground Bolted Storage tank #2 0.097 MG; 26.0 feet diam.; 24.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		275.00 150.00 425.00 1,180.00 140.00		
10.	TOTAL		2,170.00		
	Village Green Potable Water Ground Storage Tank 0.155 MG; 28.9 feet diam.; 32.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		275.00 150.00 425.00 1,430.00 140.00		
11.	TOTAL		2,420.00		
	Hills Potable Water Ground Storage Tank 3.0 MG; 90 feet diam.; 64 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		275.00 150.00 425.00 3,980.00 140.00		
12.	TOTAL		4,970.00		
	Judson Potable Water Elevator Standpipe Tank 0.25 MG; 40 feet diam.; 35 feet bowl height; 139.5 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		275.00 150.00 425.00 1,280.00 140.00		
13.	TOTAL		2,270.00		

BID NOT TABULATED
INCOMPLETE BID

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

		International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
	Marshall Potable Water Ground Storage Tank 0.55 MG; 55.0 feet diam.; 32.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		275.00 150.00 425.00 1,480.00 140.00		
14.	TOTAL		2,470.00		
	Pearsall Reuse Wate Ground Storage Tank 2.50 MG; 120.0 feet diam.; 33.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees		275.00 150.00 425.00 3,740.00 140.00 3,650.00	BID NOT TABULATED INCOMPLETE BID	
15.	TOTAL		8,380.00		
	Randolph Tank Potable Water Ground Storage Tank 5.00 MG; 1.65.0 feet diam.; 32.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		275.00 150.00 425.00 5,380.00 140.00		
16.	TOTAL		6,370.00		
	Sasse Potable Water Ground Storage Tank 2.0 MG; 92.3 feet diam.; 43.8 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation		275.00 150.00 425.00 3,250.00 140.00		
17.	TOTAL		4,240.00		

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

18.	Stotzer Reuse Water Ground Storage Tank 2.2 MG; 84 feet diam.; 51 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		275.00 150.00 425.00 3,500.00 140.00 3,650.00 8,140.00	BID NOT TABULATED INCOMPLETE BID		
19.	Walden Heights Potable Water Ground Storage Tank 0.05 MG; 26.0 feet diam.; 16.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL		275.00 150.00 425.00 1,480.00 140.00 2,470.00			
20.	Minor Repairs (Item F) Hourly Rate for 40 hours TOTAL		280.00 11,200.00			
21.	Emergency Services (Item E) 4 ea. Mobilization 60 hrs. Hourly Rate TOTAL		1,450.00 5,800.00 340.00 20,400.00 26,200.00			
	TOTAL AMOUNT FOR OPTION YEAR 2012 (ITEMS 1-21)		121,385.00			
1.	OPTION YEAR 3 Brooks Reuse Water Ground Storage Tank 0.50 MG; 54.0 feet diam.; 27.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL		285.00 170.00 440.00 1,240.00 150.00 1,250.00 3,535.00			

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

2.	<p>Cedar Creek Potable Water Ground Storage Tank 0.33 MG; 19.0 feet diam.; 17.7 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation</p>		<p>285.00 170.00 440.00 1,240.00 150.00</p>				
TOTAL			2,285.00				
3.	<p>Devine Reuse Water Elevated Storage Tank 1.20 MG; 84 feet diam.; 43 feet bowl height; overall height 126 feet Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation</p>		<p>285.00 170.00 440.00 1,650.00 150.00</p>	<p align="center">BID NOT TABULATED INCOMPLETE BID</p>			
TOTAL			2,695.00				
4.	<p>East Houston Reuse Water Ground Storage Tank 1.0 MG; 75 feet diam.; 32 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation</p>		<p>285.00 170.00 440.00 1,550.00 150.00</p>				
TOTAL			2,595.00				
5.	<p>Encino Park Old Potable Water Standpipe Tank 0.50 MG; 38.0 feet diam.; 64.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation</p>		<p>285.00 170.00 440.00 1,550.00 150.00</p>				
TOTAL			2,595.00				

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

6.	Fredericksburg Reuse Water Elevated Storage Tank 1.0 MG; 74 feet diam.; 38 feet bowl height; Overall Height 135 feet Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL	285.00 170.00 440.00 1,680.00 150.00 2,250.00 4,975.00	BID NOT TABULATED INCOMPLETE BID		
7.	Highland Hills Potable Water Elevated Standpipe Tank 1.50 MG; 96.0 feet diam.; 42.0 feet bowl height; 117 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	285.00 170.00 440.00 1,590.00 5,500.00 7,985.00			
8.	Inspiration Potable Water Vessel Storage Tank 2.20 MG; 82.8 feet diam.; 31.2 feet overall height; 142.8 inches water/level tank Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	285.00 170.00 440.00 3,250.00 150.00 4,295.00			
9.	Lions Field Potable Water Elevated Standpipe Tank 1.50 MG; 88.0 feet diam.; 46.5 feet bowl heights; 134.5 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	285.00 170.00 440.00 1,590.00 150.00 2,635.00			

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY				
14.	Oliver Ranch Potable Water Ground Storage Tank 3.0 MG; 110.0 feet diam.; 52.0 feet overall height				
	Inspection Cost Drained		285.00		
	ITEM DELETED				
	Drained Cleaning cost per additional 1" of sedimentation		170.00		
	Inspection Cost In-service (not drained)		440.00		
	Cleaning Cost In-service (not drained)		3,250.00		
	Underwater Cleaning cost per additional 1" of sedimentation		150.00		
TOTAL			4,295.00		
15.	Pearsall Reuse Water Ground Storage Tank 2.50 MG; 120.0 feet diam.; 33.0 feet overall height				
	Inspection Cost Drained		285.00		
	ITEM DELETED				
	Drained Cleaning cost per additional 1" of sedimentation		170.00		
	Inspection Cost In-service (not drained)		440.00		
	Cleaning Cost In-service (not drained)		3,050.00		
	Underwater Cleaning cost per additional 1" of sedimentation		150.00		
Sedimentation Transport fees		5,500.00			
TOTAL			9,595.00		
16.	Pipers Meadow Potable Water Ground Storage Tank 0.05 MG; 19.0 feet diam.; 24.3 feet overall height				
	Inspection Cost Drained		285.00		
	ITEM DELETED				
	Drained Cleaning cost per additional 1" of sedimentation		170.00		
	Inspection Cost In-service (not drained)		440.00		
	Cleaning Cost In-service (not drained)		1,050.00		
	Underwater Cleaning cost per additional 1" of sedimentation		150.00		
TOTAL			2,095.00		
17.	Pipestone Potable Water Ground Storage Tank 3.0 MG; 84.0 feet diam.; 75.9 feet overall height				
	Inspection Cost Drained		285.00		
	ITEM DELETED				
	Drained Cleaning cost per additional 1" of sedimentation		170.00		
	Inspection Cost In-service (not drained)		440.00		
	Cleaning Cost In-service (not drained)		3,250.00		
	Underwater Cleaning cost per additional 1" of sedimentation		150.00		
TOTAL			4,295.00		

BID NOT TABULATED
 INCOMPLETE BID

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

ITEM NO.	DESCRIPTION AND APPROXIMATE QUANTITY	International Diving Services, LLC 3311 West Division St. Arlington, TX 76012	Waterfront Divers, LLC 1601 Valley View Lane Farmers Branch, TX 75234		
18.	Roft Potable Water Ground Storage Tank 2.2 MG; 96 feet diam.; 40 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	285.00 4,095.00			
19.	Roft Potable Water Hydro-Pneumatic Tank 0.20 MG; 10.0 feet diam.; 6.5 feet Water/Level Tank; 32 feet length Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation TOTAL	285.00 455.00			
20.	Shields Potable Water Ground Storage Tank 5.0 MG; 116.5 feet diam.; 73.0 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation TOTAL	285.00 6,535.00			
21.	Stotzer Reuse Water Ground Storage Tank 2.2 MG; 84 feet diam.; 51 feet overall height Inspection Cost Drained ITEM DELETED Drained Cleaning cost per additional 1" of sedimentation Inspection Cost In-service (not drained) Cleaning Cost In-service (not drained) Underwater Cleaning cost per additional 1" of sedimentation Sedimentation Transport fees TOTAL	285.00 7,745.00			

BID NOT TABULATED
 INCOMPLETE BID

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

	Sundance Potable Water Ground Storage Tank 43,938.0 MG; 21.0 feet diam.; 16.0 feet overall height				
	Inspection Cost Drained		285.00		
	ITEM DELETED				
	Drained Cleaning cost per additional 1" of sedimentation		170.00		
	Inspection Cost In-service (not drained)		440.00		
	Cleaning Cost In-service (not drained)		1,680.00		
	Underwater Cleaning cost per additional 1" of sedimentation		150.00		
22.	TOTAL		2,725.00		
	Minor Repairs (Item F)				
	Hourly Rate for 40 hours		290.00		
23.	TOTAL		11,600.00		
	Emergency Services (Item E)				
	4 ea.		1,480.00		
	Mobilization		5,920.00		
	60 hrs.		350.00		
	Hourly Rate		21,000.00		
24.	TOTAL		26,920.00		
	TOTAL AMOUNT FOR OPTION YEAR 2013 (ITEMS 1-24)		132,350.00		
	TOTAL FOR INITIAL AWARD		91,965.00		
	TOTAL FOR EXTENSION 1		117,375.00		
	TOTAL FOR EXTENSION 2		121,385.00		
	TOTAL FOR EXTENSION 3		132,350.00		
	Terms		1% 20 days		
	Delivery Days				

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234

BID NOT TABULATED
 INCOMPLETE BID

SAN ANTONIO WATER SYSTEM
 P. O. BOX 2449
 SAN ANTONIO, TEXAS 78298-2449
TABULATION OF BIDS

PROPOSAL Annual Contract for
 FOR: Potable and Reuse Water Storage Tank Cleaning and Inspection
 TIME & (Date of Award through December 31, 2010)
 DATE: 3:00 p.m., April 13, 2010

ITEM NO. DESCRIPTION AND APPROXIMATE QUANTITY

International Diving Services
 Liquid Engineering Corp.
 Neptune Underwater Services
 Utility Service Co.
 Waterfront Divers, LLC

Demandstar
 SAWS Website

International Diving Services,
 LLC
 3311 West Division St.
 Arlington, TX 76012

Waterfront Divers, LLC
 1601 Valley View Lane
 Farmers Branch, TX 75234