

NOTICE OF SPILL FROM A WASTEWATER FACILITY

A spill from a wastewater treatment or collection facility has occurred.

INFORMATION ABOUT THE SPILL

Facility Name: Steven M. Clouse Water Recycling Center – 10137-033

Contact for further information: Anne Hayden – 210-233-3622

Location of the spill: 18-inch Sewer Main at 1000 E Olmos Dr near Olmos Basin

Estimated time and date of spill: 12:20 PM on 02/04/2020

Estimated volume of the spill (number of gallons): Spill estimated > 50,000 gallons

Type of spill: (domestic) (industrial) (other) Explain other: Domestic wastewater

Area potentially affected: Olmos Creek

Suspected cause of spill: Grease and debris

THE FOLLOWING ACTIONS HAVE BEEN TAKEN:

- ☒ Appropriate local governmental officials have been notified.
- ☒ TCEQ regional office has been notified.
- ☒ The spill has been contained.
- ☐ Increased monitoring of water supply systems has been initiated.
- ☐ The cause of the spill has been corrected.
- ☒ Clean-up activities are underway/completed.
- ☐ Other: _____

PERSONS MAY WISH TO TAKE THE FOLLOWING PERSONAL PRECAUTIONS

- ☐ Use only water that has been distilled or boiled at a rolling boil for at least one minute for all personal uses including drinking, cooking, bathing and tooth brushing
- ☒ Don't swim in affected area streams, ponds or lakes.
- ☒ Always wash hands thoroughly before preparing or eating food.
- ☒ Always wash hands thoroughly after any contact with animals, soil or diapers.
- ☒ Private well owners may wish to treat their well water, have their well water tested and inspect their wells for proper siting, construction and maintenance.